

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565


1/6

FIG 1A



100 102 104 106 108 110 112 114


FIG 1B



Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565


2/6

FIG 1C




100004794 3 3 0 1 0 1

FIG 1D




PRIOR ART



10004644-40101


FIG 3



Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565

5/6

FIG 4A



卷之三

FIG 4B




FIG 5

